




TSS Emergency Road Service Call Form726

Caller Name Sam Smith
Customer Company Name Your Town Trucking
Call Time 12-12-2016 9:00 AM
Caller or Company Email agrupa@southsidetire.biz
Call Back Number (920) 555-5555
Driver Name Tom Smith
Driver Phone Number (513) 555-5555



Type of Unit Tractor
Unit Number 726
Wheel Position LRO
Rim/Wheel Damaged YES
Tire Size 445/50R22.5
Replacement Tire Bandag B760 Fueltech
Disposition Of Off Tire Returned to Dealership and Scrapped
Tire Replacement Reason Run Under-Inflated

Remove and Install QTY
Dismount and Mount - Vehicle QTY 1
Aluminum valve Stem QTY 1
Brass Valve Stem QTY 1
Flow Through Valve Cap QTY 1
Additional Service Items 1 Hour Service Call

Roll Time 8:57 AM
Drivers Signature


Drivers Name Tom Smith
Comments Nail in crown caused it to go flat.

Photo of Unit Number



Photo of License Plate



Photo of Off Tire/s Before Work



Photo of Tire/s After Work is Complete

